

LANDBUILD

Cuckfield Operation Watershed Existing Layout



39m section of 225mm pipe between manholes in poor state, damage and root ingress

88m section of 225mm pipe unable to be surveyed because of roots/damage

Section of pipe is curved and blocked by root ingress



Cuckfield Operation Watershed Proposed Layout

